

## Lucid Discrepancy List

1. Nothing promised or due (comment by Lucid DA).
2. Trunk passenger side, gasket, fastener broken. See attached photo.
3. Plate for front license plate not installed.
4. Driver side, rear wheel well, front part, insert not properly fasten, fastener hole without fastener is visible. Take off wheel and do complete overhaul of insert and all fasteners. Look for broken or improperly installed fasteners. See attached photo.
5. Passenger side, rear bottom end of contrail, "Air" badge improperly fastened and improperly lined up with bottom of contrail. Compare with driver side that is good. See attached photo.
6. Lucid HomeLink could not be set up or does not work, customer is using manual three-button remote to be able to open/close the garage doors. HomeLink works on the customer 2014 Nissan Altima. See attached photo.
7. Charge port rubbing against fender when opening/closing. See attached photo.
8. Poor fit of bottom of closed trunk lid, ~1/4" gap difference for driver vs passenger side. See attached photos.
9. General rattle noise in the car when driving over uneven surfaces or bumps. Only ~15-30 mi/hr was tested. Alternating driving comparison between the customer 2014 Nissan Altima with ~46,000 miles on the odometer and Lucid AGT was performed. Altima featured close to none or no rattling noise whereas AGT featured quite a bit of rattling noise. The testing was performed in the customer neighborhood and to and from the grocery store where the customer typically shops.
10. Pronounced rattling noise somewhere in the rear of the car (difficult to pinpoint) when the rear passenger wheel hits uneven pavement or small bumps of decent size.
11. Trunk opening during the first inch of opening, squeaking noise.
12. Frunk during the last inch of closing, the mechanical movement seems to be rough, and it is questioned if the mechanism works properly or is properly adjusted for smooth operation. See attached photo.
13. Trunk upper interior trim with six fasteners, at least one fastener is broken, several fasteners are discolored. Fastener holes between the trunk and plastic trim do not seem to line up everywhere. At a minimum replace all fasteners. See attached photo.
14. Trunk upper part, exterior rubber gasket, does not seal everywhere. Poor fit, may leak water. See attached photo.
15. The car was locked in the garage in the evening and both FOBs were stored overnight ~25 ft away and with three house walls between the FOBs and the car. The mirrors were folded and all four door handles were closed. Both FOB were in closed Faraday's bags as recommend by other Lucid owners. When the customer came out in the morning, the driver front door handle was fully open. Note that if the FOB is not in Faraday's bag and the customer walks around in the garage with the AGT parked in the driveway, the AIR will "wake up" and "go to sleep" as the customer moves or does not move, respectively. See attached photo.
16. Lucid/EA free charging does not work. The customer tried 10/13/2022 together with the Lucid DA and only credit card payment worked. It was tried again by the customer 10/14/2022 but with the same unsatisfactory result.
17. Driver side, rear seat, seat belt cover at the upper end of the seat belt is misaligned. Compare with the passenger side that is perfect. See attached photo.
18. Passenger side, front seat, bottom cover at the bottom of the seat belt and seat, poor fit, large gap. Compare with driver side that is not perfect but acceptable. See attached photo.
19. Driver side, front wheel well, bottom rear part, insert and fastener is loose. Take off wheel and do complete overhaul of insert and all fasteners. Look for broken or improperly installed fasteners. See attached photo.
20. Passenger side, front wheel well, several fasteners for the insert are missing. Take off wheel and do complete overhaul of the insert and all fasteners. Look for broken or improperly installed fasteners.
21. Written receipt or proof that wheel alignment has occurred and is within tolerance specifications.