

Concern: Customer states hearing a clicking noise when turning the wheel from the suspension area. Test drive needed. Check and advise.

Cause: Verified customer concern. Technician was able to hear a slight clicking noise from the front of the vehicle when making tight turns at slow speeds due to worn camber links.

Corrections: Technician removed and replaced the front camber links following all service procedures and torquing all hardware to spec. Four wheel alignment performed. Verified on test drive that clicking noise is no longer present.

Old Left Camber Link PN P11-S51AL0-04 SN S00306 2205600439

Old Right Camber Link PN P11-S51AR0-04 SN S00306 2206000238

New Left Camber Link PN P11-S51AL0-05 SN S00306 2306900324

New Right Camber Link PN P11-S51AR0-05 SN S003062306100289

Technician IDs:

Labor	Description	Action	Total Price	
Both Front Camber Links	Both Front Camber Links	Remove and Replace	0.0	
Part Number	Part Description	Quantity	Unit Price	Total Price
P00-F333DD-00	NUT M14-1.5 10 STEEL FLANGE LOCK Zn/Ni	2.00	\$0.00	\$0.00
P00-F336DD-00	NUT M16-2 10 STEEL FLANGE NYLON LOCK Zn/Ni HEX	2.00	\$0.00	\$0.00
P11-S51AR0-05	ASSY FRONT CAMBER LINK RIGHT	1.00	\$0.00	\$0.00
P11-S51AL0-05	ASSY FRONT CAMBER LINK LEFT	1.00	\$0.00	\$0.00